


拆除范围用地控制点坐标					
控制点	X	Y	控制点	X	Y
J1	516979.711	2501510.351	J22	517065.107	2501572.303
J2	516911.593	2501555.631	J23	517066.422	2501568.403
J3	516949.536	2501567.690	J24	517062.971	2501567.765
J4	516956.093	2501575.411	J25	517069.519	2501559.826
J5	516960.958	2501593.588	J26	517130.006	2501185.717
J6	516962.156	2501620.030	J27	517095.607	2501158.261
J7	516958.921	2501620.101	J28	517081.931	2501150.982
J8	516958.281	2501631.478	J29	517050.727	2501158.128
J9	516959.112	2501639.380	J30	517042.962	2501159.217
J10	516987.267	2501642.384	J31	517042.467	2501159.405
J11	516990.188	2501637.462	J32	517042.592	2501159.797
J12	516991.251	2501636.258	J33	517042.119	2501160.188
J13	516994.981	2501628.557	J34	517041.645	2501161.162
J14	516997.687	2501615.333	J35	517041.131	2501160.777
J15	517007.532	2501607.190	J36	517047.720	2501163.031
J16	517022.563	2501603.061	J37	517039.205	2501161.598
J17	517036.479	2501606.538	J38	517036.257	2501168.130
J18	517041.268	2501607.235	J39	517025.116	2501180.536
J19	517046.187	2501606.510	J40	517011.339	2501195.879
J20	517056.118	2501585.876	J41	516995.808	2501555.302
J21	517065.758	2501572.837			

说 明

拆除范围内现状建筑建成年限超过15年，主要为框架结构，多为1-4层，建筑质量差，存在消防安全隐患。现状无危房。

- 图 例**
- 拟拆除范围
 - 物业权利人房屋位置
 - 建筑物编号



龙岗区横岗街道深坑瑞兴手袋厂城市更新单元拟拆除范围图

